Approved For Releas (2) P3/05/20 RHA-RDP78B04560A000600010034-5

Copy 93

13 Pages

PHOTOGRAPHIC INTERPRETATION RELAXIONS

PHOTOGRAPHIC INTERPRETATION RELAXION RELAXIO


TYPE III SOVIET ICBM LAUNCH SITES












DECLASS REVIEW BY NIMA / Dod NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER



TOP SECRET

Approved For Release 2003/06/20 : CIA-RDP78B04560A000600010034-5

5X

PHOTOGRAPHIC INTERPRETATION REPORT

TYPE III SOVIET ICBM LAUNCH SITES

NPIC/R-117/63 July 1963

NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER

Next 1 Page(s) In Document Exempt

TOP SECRET | Approved For Release 2003/06/20 : GIA-RDP78B04560 A000600010034-5

NPIC/R-117/63




FIGURE 2. CONCEPT OF TYPE III ICBM SITE IN MIDSTAGE OF CONSTRUCTION.

DETAILED DISCUSSION


As the midstage of construction of a Type III launch site commences, the characteristic rectangular excavation with its associated notch is present (Figure 2). This excavation varies in size from site to site depending on soil characteristics, but generally measures about 500 by 150 feet in the main section, with the notch being on a slightly higher level and measuring 200 by 150 feet. It appears that construction is probably started nearly concurrently on the control bunker in the notch of the excavation and on three silos in the main portion of the excavation. The control bunker generally measures 120 by 100 feet and is located 90 feet to the rear of the silos. The three silos are separated by a distance of 180 feet on center, in a straight line along the approximate center line of the main excavation. These three silos do not appear consistently the same on the photography, a matter to be discussed in later paragraphs. Later, two rectangular equipment and/or fuel bunkers appear, each between two of the silos. These bunkers each measure 70 by 50 feet. It has been determined that the two objects in the excavation forward of the control bunker which were identified as silos in earlier reports are in fact the two equipment bunkers.

Also present in a midstage of construction at Type III sites is a probable covered spray pond, generally located to the rear and slightly to the left of the control bunker and measuring approximately 150 by 100 feet. Two probable buried tanks are located to the left of the control bunker and silos in an area that will eventually be enclosed by the site service road.

25X1

Approved For Release 2003/06/20: CIA-RDP78B04560A000600010034-5

NPIC/R-117/63



A canted square perimeter, 55 feet on a side, has been observed around the right and center silos or three occasions at sites in a midstage of construction. This was noted at Site D2,

TIMIC, on Site F, Verkhnyava and Site A, Olovvannava

25X1

25X1D

25X1D

25X1D

25X1B 25X1B

25X1D

25X1D**

Salda, on ICBM Complex.

In only one case has it been possible to measure the inside diameter of a silo with any degree of confidence. This was accomplished at the cener silo of Site D2, TTMTC, on

with the resultant being an inside diameter of 30 feet.

The left silo has never been seen in a midstage or construction as having a distinct snape even on he best available photography. However, in three cases it can be described as being

25X1B 25X1B

> kers have been identified at Sites F and G at the Verklinyaya Salda ICBM Complex and at Site DL. TIMIC.

Equipment bun-

TOP SECRET Approved For Release 2003/06/20 : CIA-RDP78B04560A000600010034-5

NPIC/R-117/63

| - | | | |
|---------|--|--|-------|
| | slightly larger and more massive in appearance | 76/63 for a full description of hardened IRBM/ | |
| | than the center and right silos. This was ob- | MRBM launch sites). | |
| | 25X1Dserved at Site D2, TTMTC, on | A characteristic racetrack-shaped road | |
| | 25X1D Olovyannaya, Site A, on and at | pattern is present, the long axis of which is ap- | |
| | 25X1DVerkhnyaya Salda, Site F, on The | proximately 850 feet in length. At Site D1, | |
| - | left silo can in no case be described with | TTMTC, and at Site E, Yurya ICBM Complex, a | |
| | confidence as being smaller than the other | short spur may turn in from this road and | |
| | two. | terminate at the left silo. No such spur can be | |
| - | At two of the sites in a midstage of con- | identified leading to either of the other silos. | |
| | 25X1D struction (Site G, Verkhnyaya Salda on | On the other hand, this appearance may simply | |
| | and Site F, Verkhnyaya Salda, on | be the limits of the hardstand that surrounds all | |
| - | 25X1D there has been evidence of possible con- | three silos. | |
| | necting passageways between the control bunker | The control bunker is mounded with the | |
| | and the three silos and two equipment bunkers. | mounded area measuring up to 180 by 110 feet. | |
| - | These possible passageways appear to run the | In no case can an entrance into the control bun- | |
| | length of the main excavation, with connecting | ker be identified with any degree of confidence. | |
| | segments to the actual facilities within the launch | The probable spray pond can be identified to the | |
| -1950 | site. | rear and to the left of the control bunker, and | |
| | When completed there are only a few com- | the racetrack-shaped road encircles the area | |
| | ponents of a Type III site that are identifiable | where the two probable buried tanks are located. | |
| ****** | (Figure 3). The most apparent items are three | The equipment bunkers are not visible, having | |
| | objects each identical to the other in appearance | been completely covered when the excavation was backfilled. The only indication of their | |
| | and each measuring 80 by 40 feet. These three | presence (at Site F, Verkhnyaya Salda, on | 25X1D |
| - 5-644 | items are positioned at the exact location of the | occurred when the snow was melted | 25X1D |
| | three silos seen in a midstage of construction | at a point directly over their location, probably | 20/10 |
| فسير | and are canted to the long axis of the excavation | indicating that vents of some type were dis- | |
| | location and coincide with the angle of the | charging heat at those points. | |
| | canted square perimeter observed around some | that ging heat at those points. | 0EV4D |
| - | of the center and right silos. It is noteworthy | | 25X1B |
| | that the probable portal silo located to the left and rear of the control bunker at hardened | | |
| | IRBM/MRBM launch sites is identical in appear- | | 25X1B |
| | ance when completed to the missile silos | | |
| | forward of the control bunker (see NPIC/R- | | |
| | forward of the control punker (see 141 10) h | | |
| | | | |
| | CITE DEC | CRIPTIONS | |

SITE DESCRIPTIONS

This section presents detailed descriptions of Type III launch sites that have had coverage of sufficiently good quality to be of value in the preparation of this report.

LAUNCH SITE D1, TTMTC (Figure 4)

Coverage of this site on provides the best example of a completed Type III

25X1D

- 5 -

25X1D

25X1

25X1**⋑**

NPIC/R-117/63

25X1D




FIGURE 4. LAUNCH SITE DI, TTMTC.

SILOS

EQUIPMENT
BUNKERS U/C

CONTROL BUNKER
U/C

PROB
SPRAY POND U/C

POSS WATERLINE

BLACKTOP
ROAD

100 0 400
FEET (APPROX)

FIGURE 5. LAUNCH SITE D2, TTMTC.

faunch site to date. The typical racetrack-shaped road pattern measures 900 by 350 feet and encloses most of the basic components of the site. The three silo covers or cover housings are the most apparent items present and their camed rectangular shape is clearly visible. The long axis of the covers are canted 45 degrees to the long axis of the original excavation. The covers appear to rise a few feet above the surrounding flat hardstand. The mounded control bunker is observed as is the covered probable spray pond to the left and rear of the control bunker. Two semiburied tanks are located to the left of the silos inside of the racetrack perimeter road.

(Figure 5)

25X1D

25X1

As photography of Site D1 at Tvura Tam on was the best coverage to date of a completed Type III site, the coverage of Site D2,

TTMTC on provided the best photogr phy to date of this type of site in a midstage o' construction. Plainly visible in the typical notched excavation are the three silos, the two equipment bunkers, and the control bunker. The center and right silos definitely have a cantee, square perimeter measuring approximately \$5 feet on a side. The inside diameter of the center silo measures 30 feet. Conversely, the left silo definitely does not have a canted square perimeter, and the relatively indistinct image of this silo does not lend itself to determining is exact shape. Due to the excellent photography available of this site, it is believed that this lack of definition is due to the fact that the left silo actually did not have a distinct thape at the time of this coverage. It can be state 1, though, that the left silo appears somewhat larger than the other two at this site.

Also visible at the site is the excavation for the two somiburied tanks to the left of the silos.


6 -

25X1D

25X1D

25X1

NPIC/R-117/63






FIGURE 6. LAUNCH SITE F, VERKHNYAYA SALDA.

The probable spray pond is under construction to the left and rear of the control bunker.

LAUNCH SITE F, VERKHNYAYA SALDA (Figure 6)

Coverage of this launch site or

25X1D

provides one of the best examples of a Type III site in a midstage of construction. On this photography all three silos, the control bunker, and the two equipment bunkers are visible. The center and right silos each have a suggestion of the typical canted square perimeter confirmed at Site D2, TTMTC. The left silo definitely appears somewhat larger and more rounded. A possible ramp extends from the forward edge of the main excavation to the center silo. Possible passageways approximately 15-20 feet in width extend for a distance of 300 feet along the length of the main excavation between the silos and the control bunker. Short segments running perpendicular to

the possible long passageway may interconnect




FIGURE 7. LAUNCH SITE G, VERKHNYAYA SALDA.

25X1

- 7 -


25X1


25X1

25X1

NPIC/R-117/63

25X1D





HOURT & LAUNCH SITE C, PLISETSK

the silos, equipment bunkers, and control bunker.

EAUNCH SITE G, VERKHNYAYA SALDA (Figure :)

25X1D 25X1D

This site has been observed on excellent photography in a midstage of construction The control bunker and the left equipment bunker are visible as are the three silos. The silos, however, are poorly defined, There are indications that the right equipment bunker is in an early stage of construction. A possible passageway extends almost the entire length of the excavation between the silos and the control bunker. Two objects, probably ramps to assist in construction, extend from the forward edge of the excavation to the center and left silos. These are placed, with respect to the main excavation, at the same angle that the silo covers will have when the site is completed. Forward and outside of the main excavation, three parallel unidentified linear objects were

noted. In imaginary extension of these objects leads directly to each of the silos. As previously stated, to shape can be assigned to any of the silos at his site.

LAUNCH SITE C, PLESETSK (Figure 8)

Although there were repeated

| coverages of this site while it was in a midstage | | | |
|--|--|--|--|
| of construction, none of them were of sufficient | | | |
| quality o determine shapes of the objects in | | | |
| the excaration. Identification of the silos and | | | |
| control bunker was possible on some missions, | | | |
| but only by comparing the earlier coverage with | | | |
| excellent quality photography provided by | | | |
| By this time the site had been com- | | | |
| pleted. | | | |
| On the excellent coverage provided by | | | |
| nree rectangular silo coversare | | | |
| plainly v sible. The location of the buried control | | | |
| bunker is apparent as is the typical Type III road | | | |
| pattern, but details of these features are partially | | | |

25X1D

25X1D


25X1D

25X1D

")P GHERET

TOP SECRET Approved For Release 2003/06/20 : CIA-RDP78B04560A000600010034-5

NPIC/R-117/63



PROB FENCE

SPOIL ROAD

SILOS U/C

PROB TANKS

PROB SPRAY POND

THE TIME TO THE TANKS BUNKER U/C

PROB SPRAY POND

THE TIME TO THE TIME TO THE TANKS BUNKER U/C

FIGURE 9. LAUNCH SITE A, OLOVYANNAYA.

25X1

25X1D

25X1D

25X1D

25X1D

silos.

FIGURE 10. LAUNCH SITE B, SHADRINSK.

obscured by snow cover. There is activity at the point within the road pattern analagous to the location of the two buried tanks at Launch Complex D, TTMTC, and the probable spray pond is evident to the left and rear of the control bunker.

On a number of unidentified dots are apparent forward of the center silo, down the hill toward the site fence line. These may possibly be caused either by snowmelt due to an undetermined cause or by the dumping of material in small piles on top of the snow.

On backfilling of this site appeared to be completed. On this coverage three parallel objects were observed forward of the silos similar to the ones that were noted at Launch Site G, Verkhnyaya Salda, on however, they are located closer to the

LAUNCH SITE A, OŁOVYANNAYA (Figure 9)

This site was observed in a midstage of

construction on The three silos are visible, with the right and center ones appearing vaguely canted and square. The left silo appears slightly larger and somewhat elliptical, with the major axis approximately 90 feet in length across the short axis of the main excavation. Neither the control bunker nor the equipment bunkers are present as yet.

LAUNCH SITE B, SHADRINSK (Figure 10)

As seen in a midstage of construction on fair-quality photography from this site had the characteristic notched excavation of a Type III launch site. The three silos under construction were barely visible in the main portion of the excavation; however, no shape could be assigned to any of them. The base of the control bunker had been placed in the notch but neither of the equipment bunkers was as yet present. The probable spray pond can be discerned to the rear and left of the control bunker.

25X1

25X1D

25X1D

25X1

Approved For Release 2003/06/20 : QIA-RDP78B04560A000600010034-5


MPIC/R-L17/63

LAUNCH SITE E, YEDROVO (Figure 1)

25X1D

The rectangular shape of the three silo covers can be barely observed on photography of this completed site from The typical road pattern of a completed site is present but snow cover prevents detailed interpretation of the site.

The snow is melted over the location of the equipment bunkers, indicating a discharge of heat at this point. The snow is also melted at a point to the left of the left silo beyond the boundary of the original excavation. The location of this melted snow coincides exactly with a small structure that was observed outside of the excavation when the site was in a midstage of construction. The characteristic road pattern cannot be definitely traced because of the snow cover; however, a faint suggestion of it does show through the snow.



IGURE 11. LAUNCH SITE E, YEDROVO.

- (() -

TOP SECRET Approved For Release 2003/06/20 : CIA-RDP78B04560A000600010034-5

NPIC/R-117/63

REFERENCES

| | PHOTOGRAPHY |
|--|--|
| | |
| - | |
| - | |
| 25X1D | |
| - | |
| 1 | |
| -acedi | |
| - | RELATED DOCUMENTS |
| and the same of th | NPIC. R-30/63, Silo ICBM Launch Areas in the USSR, Mar 63 (TOP SECRET NPIC. R-48/63, Launch Complex D, Tyura Tam Missile Test Center, USSR, Apr 63 (TOP SECRET NPIC. R-76/63, Analysis of Hardened MRBM/IRBM and IRBM Launch Sites in the USSR, Apr 63 (TOP SECRET |
| ? - | REQUIREMENTS |
| ~ | DIA. XX 63-68 CIA. RR/99/63 |
| _ | NPIC PROJECT J-94/63 |

- 11 -

25X1 25X1 25X1

| Approved For Release 2008/08/20 REIA-RDP78B04560A000600010034-5 | |
|---|--|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |